



ASSEMBLY INSTRUCTIONS

Pallet rack support bar

PRWA800
PRWA1100



Please read this manual before using the product and follow the instructions it contains!

TECHNICAL DATA

Type	Unit	PRWA800	PRWA1100
Width	mm	851	
Depth	mm	936	1236
Height	mm	99	
Width (usable area)	mm	814	
Depth (usable area)	mm	917	1217
Height angled panels	mm	59	
Angle	°	15	
Material thickness	mm	2	
Max. load per module	kg	300	
Weight	kg	7	9
Colour		Silver	
Material		Steel	
Surface finish		Hot-dip galvanised	

PARTS LIST

	Description	Quantity	Image
A	Right angle support	1	
B	Left angle support	1	
C	Cross brace	2	
D	M6x25 Screws	4	
E	M6 Washer	4	
F	M6 Lock nut	4	

ASSEMBLY



Important note

Place the angle supports on the floor with the open side of the profile facing upwards. This is the only way to access the screw holes and fit the cross struts without any problems.

No.	Description	Image
1	Place the right-angle support (A) and left-angle support (B) on the floor, parallel to each other the open side of the profile facing downwards	
2	Position both cross-braces (C) between the angle supports (A + B)	
3	Refer to the markings in the image on the right; insert one screw (D) through each angle support (A + B) and cross brace (C), and tighten them slightly using a washer (E) and a lock nut (F)	
4	Align all parts and then tighten all four screw connections firmly	
5	Turn the finished angle support over and fit it in place	

SERVICE & CONTACT

Contact our product experts and find help and solutions for your product. Here you will find all contact information listed by country and language: www.topregal.co.uk/en/service

Responsible for the content:

TOPREGAL GmbH
Industriestrasse 3
70794 Filderstadt
GERMANY
www.topregal.com

TOPREGAL

